

**From:** [Wallingford, Jonni B.](#)  
**To:** [Sheldrake, Sean](#); [Zhen, Davis](#); [Young, Hunter](#)  
**Cc:** [younghs@cdmsmith.com](mailto:younghs@cdmsmith.com); [Vickstrom, Kyle E.](#); [Scott Coffey](#)  
**Subject:** Sediment Trap Oversight  
**Date:** Tuesday, January 29, 2019 12:13:52 PM  
**Attachments:** [IMG\\_20190129\\_113754651\\_HDR.jpg](#)  
[IMG\\_20190129\\_114919253\\_HDR.jpg](#)  
[IMG\\_20190129\\_114952611\\_HDR.jpg](#)  
[IMG\\_20190129\\_114943650\\_HDR.jpg](#)  
[IMG\\_20190129\\_103839877\\_HDR.jpg](#)  
[IMG\\_20190129\\_112326729\\_HDR.jpg](#)  
[IMG\\_20190129\\_112417883\\_HDR.jpg](#)  
[IMG\\_20190129\\_110902131\\_HDR.jpg](#)  
[IMG\\_20190129\\_111405065\\_HDR.jpg](#)

---

Hello,

The Pre-RD group has retrieved ST07B (RM 16.2 West Bank). One tube was found broken with some sediment remaining at the bottom. They plan to cap the broken tube and duct tape the top to try and preserve any sediment left in the tube for a possible "flagged" sample (photo1). Excess water and sodium azide from the tubes (photo 2) were drained into a 5 gallon bucket to be containerized and disposed of at the processing warehouse. The tubes were then capped and sealed with foil (photo 3) and will be placed in the white PVC pipes (photo 4) on ice.

Jonni

(b) (6)

Photo 1: traps retrieved from water. 4th trap broken



Photo 2: Sodium Azide decanted from tubes into bucket



Photo 3: tubes are capped and sealed with foil



Photo 4: PVC pipes to store tubes on ice (back bucket), front bucket: new trap tubes ready to deploy at next location (7E)



Diver communication station, live video feed



Diver donning suit before retrieving ST07W. View of NRC Vessel from Cayuse



Get [Outlook for Android](#)